



HARDNESS CONVERSION GUIDE

Table with 4 columns: N/mm², HV, HB, HRC. Values range from 200 to 675 N/mm².

Table with 4 columns: N/mm², HV, HB, HRC. Values range from 680 to 1180 N/mm².

Table with 4 columns: N/mm², HV, HB, HRC. Values range from 1190 to 1740 N/mm².

Table with 4 columns: N/mm², HV, HB, HRC. Values range from 1750 to 2200 N/mm².